

Date	System	Codes	Description	Status
2/2/2019	CAV	U0001-82	High speed CAN communication bus	intermittent
2/2/2019	IPMB	U0140-08	Lost communication with body control module	intermittent
2/2/2019	FCIM	U0164-00	Lost communication with heating ventilation and AC control module	intermittent
2/2/2019	IPC	U0164-00	Lost communication with heating ventilation and AC control module	intermittent
2/2/2019	IPC	U0184-00	Lost communication with audio unit	intermittent
2/2/2019	IPC	U025D-00	Lost communication with front controls interface module 'B'	intermittent
2/2/2019	FCIM	U0424-68	Invalid data received from heating, ventilation and air conditioning control module	intermittent
2/18/2019	GWM	B13C5-92	secondary battery	intermittent
2/18/2019	ACM	B1D55-13	Antenna 2 circuit	intermittent
2/18/2019	CAV	U0001-82	High speed CAN communication bus	intermittent
2/18/2019	CAV	U0001-87	High speed CAN communication bus	intermittent
2/18/2019	CAV	U0011-87	Medium speed CAN communication bus performance	intermittent
2/18/2019	IPMB	U0140-08	Lost communication with body control module	intermittent
2/18/2019	FCIM	U0164-00	Lost communication with heating ventilation and AC control module	Historic
2/18/2019	IPC	U0164-00	Lost communication with heating ventilation and AC control module	Historic
2/18/2019	ICP	U0184-00	Lost communication with audio unit	Historic
2/18/2019	ICP	U025D-00	Lost communication with front controls interface module 'B'	Historic
2/18/2019	FCIM	U0424-68	Invalid data received from heating, ventilation and air conditioning control module	Historic
2/18/2019	PCM	U0447-00	Invalid data received from gateway A	Historic
2/18/2019	CAV	U1A4B-47	Control module microprocessor B	intermittent