

Vehicle diagnostic report



Shop Name:
Address:
Telephone:
Email :
Fax:

Owner name: James Zigga

Make: LANDROVER_DC

Model:

Year:

VIN: SALAE25456A372765

Mileage: 246332km

Vehicle Software Version: V33.47

Diagnostic Application Version: 2.2.9

Test Time: 2020-01-05 10:56:59

Tester: iLand

Diagnostic path: Discovery 3 > Normal Aspirated Petrol V8 > Health Report

Diagnostic Result

Fault		(11)
ECM (Engine Control Module)	(4)	Abnormal
	P0101-00 Mass or volume air flow - circuit range/performance	Historic
	P0172-00 System too rich (bank 1)	Historic
	P0175-00 System too rich (bank 2)	Historic
	P0579-00 Speed control multi-function input A - circuit range/performance	Intermittent
TCM (Transmission control module)	(1)	Abnormal
	U0155-87 Lost communication with instrument cluster control module	Permanent
IPC (Instrument cluster control module)	(2)	Abnormal
	U0102-87 Lost communication with transfer case control module	Intermittent
	U0132-87 Lost communication with ride level control module	Intermittent
RLM (Ride level control module)	(2)	Abnormal
	U0416-86 Invalid data received from vehicle dynamics control module	Pending
	C1A07-62 Cross articulation	Intermittent
ATCM (All terrain control module)	(3)	Abnormal
	U0416-94 Invalid data received from vehicle dynamics control module	Pending
	U0403-94 Invalid data received from transfer case control module	Pending
	U0421-94 Invalid data received from ride level control module	Historic
RDCM (Rear differential control module)	(3)	Abnormal

	P0122-87 Throttle/pedal position sensor A - circuit low input	Intermittent
	P080A-00 Clutch position is not learnt	Permanent
	P186D-00 Clutch actuator is stuck	Intermittent
VDM (Vehicle dynamics control module)	(2)	Abnormal
	U1A4A-68 Invalid data received from differential control module - rear	Intermittent
	U0132-87 Lost communication with ride level control module	Intermittent
AAM (Audio amplifier module)	(1)	Abnormal
	B1A96-68 Bus still active after shutdown request	Intermittent
BCM (Body control module)	(5)	Abnormal
	B1B02-28 Low frequency coil	Permanent
	B1C57-14 Unused relay drive.	Intermittent
	B1D12-15 Volumetric alarm power circuit	Intermittent
	B1D13-15 Interior lamps 1 circuit	Intermittent
	U0155-87 Lost communication with instrument cluster control module	Intermittent
PAM (Parking assist control module)	(1)	Abnormal
	B1B52-96 Rear sounder	Permanent
TEL (Cellular telephone control module)	(1)	Abnormal
	B1A00-47 Control module	Permanent
Normal	(7)	
SRS (Supplemental Inflatable Restraint System)		Normal
SASM (Steering angle sensor module)		Normal
PBM (Parking brake control module)		Normal
TCCM (Transfer case control module)		Normal
ACM (Audio front control module)		Normal
FEM (Front entertainment control module)		Normal
HVAC (Heating ventilation and air conditioning control module)		Normal